

Indianapolis Division 6964 Hillsdale Ct. Indianapolis, IN 46250

Tel: (317) 842-4261 Fax: (317) 842-4286

ANALYTICAL REPORT

Mr. Richard Tyler MILBANK MANUFACTORING INC 1400 E. HAVENS ST. KOKOMO, IN 56901-3188

04/27/1998

NET Job Number: 98.02534

Page 1 of 3

Enclosed are the Analytical Results for the following submitted to NET, Inc. Indianapolis Division for analysis:

Project Description: TWICE WEEKLY WASTEWATER

Sample Number Sample Description Date Taken

Date Received

204704

OUTFALL 001

04/14/1998

04/14/1998

National Environmental Testing, Inc. certifies that the analytical results contained herein apply only to the specific samples analyzed.

Reproduction of this analytical report is permitted only entirety.



Indianapolis Division 6964 Hillsdale Ct. Indianapolis, IN 46250

Tel: (317) 842-4261 Fax: (317) 842-4286

ANALYTICAL REPORT

Mr. Richard Tyler MILBANK MANUFACTORING INC 1400 E. HAVENS ST. KOKOMO, IN 56901-3188

04/27/1998

Sample No.: 204704 Job No.: 98.02534

P.O. NO.:

Page 2 of 3

Sample Description: OUTFALL 001

Job Description: TWICE WEEKLY WASTEWATER

Date Taken: 04/14/1998

Date Received: 04/14/1998

<u>Parameter</u>	Result	<u>Flaq</u>	<u>Units</u>	Analyst/ <u>Date of Analysis</u>	Method <u>Number</u>	Reporting Limit
Iron, ICP	0.49		mq/L	tjg / 04/15/1998	E-200.7	<0.10
Lead, ICP	<0.080		mg/L	tjg / 04/15/1998	E-200.7	<0.10
Silver, ICP	<0.010		mg/L	tjg / 04/24/1998	E-200.7	<0.010
Zinc, ICP	3.4		mg/L	tjg / 04/15/1998	E-200.7	<0.020



Indianapolis Division 6964 Hillsdale Ct. Indianapolis, IN 46250

Tel: (317) 842-4261 Fax: (317) 842-4286

FIELD REPORT

JOB #: 98.02534

CLIENT: MILBANK MFG.

PROJECT: TWICE WEEKLY WASTEWATER

DATE: 4/14/98 SAMPLER(S): MTM

An ISCO model 6700 auto sampler was used in the composite mode of operation. The sampler was equipped with a plastic composite jug, tygon suction line, battery, ice, and strainer.

All reusable equipment is decontaminated with alconox, tap water, 5% nitric acid, and deionized water. New tygon suction tubing was used for the sampler. A stainless steel strainer was also used for the sampling event.

The sampler was set to take a sample every 30 minutes for 24 hours.

Monitoring start 8:00 on 4/13/98 Monitoring end 8:00 on 4/14/98

The composite sample was cloudy, pale yellow in color.

Notes: Samples were preserved, in the field, in the appropriate containers with any required preservative.



	PROJE(CT NU	MBE	R							ASTEL	NATE			INVOICE TO:		
						PHONEFAX											
PRINT NAME)	la	lage					METALS: Ph.Fe, Ry, 2n FIELO REDORT			ANALYSES			NET QUOTE NO				
DATE TIME SAMPLE ID/DESCRIPTION		MATRIX	COMP	HCI	# and Con	d Type ntainer	S S S S S S S S S S S S S S S S S S S	METALS: PL F	FIELD REDOR						enforcement action? Which regulations apply: RCRA NUST Other	Drinking Water None	
1/13.4/14 OUTFALL 001		در	٧			1			X		+						
					+												
· · · · · · · · · · · · · · · · · · ·					1												
					+												
					+		+										
CONDITION OF SAMPLE: BOTTLES INTACT?	YBS/NO			C	OC SI	EALS	PRE	ESENT	AND	INTAC	TZYE	5/NO			TEMPERATURE UPON RECEIPT: Bottles supplied by NET?	1.2 0	
SAMPLE REMAINDER DISPOSAL: RETURN SA	MPLE REMAIN NET TO DISPO			LIEN	T VIA										DATE		
LINQUISHED BY: DATE TIME RECEIVED BY: 4/14/8 8 15:00 REMARKS:					R	RELINQUISHED BY: DATE TIME RECEIVED FOR NET BY: 114 98 1500											